

**SHE Alerts 0052**

SECTION

SUB-SECTION

SUBJECT

SHE Management

Incident Investigations

SHE Incident Alerts

Doc. No.

Revision

Effective Date

Page No.

3800/FOR/0052

01

11.12.2019

1 of 1

Safety First !**SHE Alert****Safety Communication****Pictures****Classification**

First Aid Injury and
Environmental incident

Where?**Section:**

Solar Ponds

Equipment:

3 Edgeworks trucks

When?

Date: 07/10/2021

Time: 0830 hrs

Incident Description

An Edgeworks Inc tipper truck (S26) hit a water bowser and tipper truck (S25) which had stopped in the middle of the haul road between NS and X1 ponds.

Body part / Nature of Damage

- 100L of diesel spilled on the haul road
- S26 truck operator sustained right hip joint sprain and multiple bruises.

Preliminary Findings?

- Operators were also tested and the results were negative.
- All operators were in possession of valid authorizations.
- Pre Start Checklists of the trucks were done.
- Non adherence to Use of Company Vehicle Procedure;
 - Water bowser and tipper truck (S25) stopped in the middle of the haulage road.
 - Skid marks (20m) from tipper truck (S26) indicate that the truck was travelling above the stipulated 40 km/hr.

Corrective and Preventative Actions

- The activity was immediately stopped, and relevant authorities were notified.
- The injured was taken to the clinic for further assessment
- Edgeworks Inc employees were briefed on the incident and Use of Company Vehicles Procedure.
- The contaminated soil was removed and taken to Salvage Yard.
- Employees must adhere to safety procedures.
- Supervisors must enforce safety procedures in their areas of responsibility.

