

**Safety First !****SHE ALERT****SAFETY Communication****Pictures****Classification**

Property Damage

Where?**Section:**Fabrication
Workshop**Equipment:**

Vehicles

Incident Description

The two vehicles collided whilst both were reversing, one was departing and the other was attempting to park at the Fabrication workshop.

Preliminary Findings?

- Drivers' authorization for both drivers is valid.
- Vehicle pre-start checklists were conducted.
- Drivers were also tested and results were negative.
- Non-adherence to procedure- The driver departing workshop had not parked in reverse as required.

When?**Date:** 10/09/2021**Time:** 1420 hrs.**Body part / Nature of Damage**

Door panel and rear bumper

Corrective & Preventative Measures

1. Activity was stopped immediately.
2. Incident scene was secured.
3. Incident was reported to relevant authorities
4. Employees should always adhere to procedures.

