

**Safety First !****SHE ALERT****SAFETY Communication****Pictures****Classification**

Property Damage

Where?**Section:**

Rigging Workshop

Equipment:

Shuttle Lift (Small Crane)

Incident Description

Whilst loading a 5 meter wire sling on top of the shuttle lift's platform the sling hit the windscreen.

Preliminary Findings?

- The rigger was also tested and the results were negative.
- The rigger was not attentive whilst putting the sling top of the shuttle lift's platform.
- The sling hit the front windscreen and cracked it.

When?**Date:** 13/09/2021**Time:** 1300 hrs**Body part / Nature of Damage**

Cracked front windscreen

Corrective & Preventative Action

- The activity was immediately stopped.
- The incident was reported to the relevant authorities.
- Employees of the section were briefed on the incident.
- Employees must always be attentive when they execute their duties.

