SHE Management Incident Investigations SHE Incident Alerts

Doc. No. Revision **Effective Date** Page No.

3800/FOR/0052

11.12.2019 1 of 1

Safety First!

SHE ALERT

SAFETY Communication

Pictures

Classification

First Aid

Where?

Section:

Soda Ash Compaction

Equipment:

When?

Pre-Roller Crushers

Incident Description

A Plant Operator's 4th right finger got trapped between the v-belt and pulley whilst trying to reverse the crusher manually.

Body part / Nature of Damage

Date: 25/06/2021 Time: 1900 hrs.

4th Right Finger

Corrective & Preventative Measures

- 1. Activity was stopped
- 2. Incident was reported to the relevant authorities
- The injured was taken to the mine clinic for further assistance
- 4. Brief all employees of the section
- Replace all damaged guards within the plant.
- 6. Tampering with protective devises is prohibited.

Preliminary Findings?

The Plant Operator did not follow the operating process of reversing and forwarding the crusher at the sub station when there is a choke.

The injured tried to reverse the crusher by pulling the V belt manually as opposed to using the crusher reverse mechanism at the sub station.

Most of the guards at the Soda Ash Crushers have been damaged, this is unsafe as it exposes employees to rotating machinery which can cause serious injuries.

