

SHE Alerts 0052
SECTION
SUB-SECTION

SUBJECT

SHE Management
Incident Investigations
SHE Incident Alerts

Doc. No.
Revision
Effective Date

Page No.

3800/FOR/0052 01

11.12.2019 1 of 1

Safety First!

Classification

Property Damage

Location: Portable

Tshwane turn

Section: Civils

Water pipeline – Near

SHE ALERT

Incident Description

Whilst positioning a TLB to excavate a trench for installation of portable water pipeline, the rear wind screen of the TLB got shattered.

Safety Communication

Preliminary Findings?

- Defective Equipment- The TLB back wind screen shuttered whilst the equipment was in operation.
- The operator had a valid authorization.
- The operator was alco tested and results were negative.

When?

workshop

Where?

Date: 5/05/2023

Time: 16:20hrs

Body part / Nature of Damage

Shattered wind screen of the TLB

Preventative & Corrective Measures

- The incident was reported to responsible personnel
- The incident was briefed to employees of the section.
- Garage to engage in the Original Equipment Manufacture (OEM) to establish possible causes for defects in mobile machinery.

Shattered wind screen of the TLB

