

Safety First!

Property Damage

Classification

Location: WIO

Section: Stores

Date: 18/01/2024

Time: 1040hrs

Warehouse

Where?

When?

SHE Alerts 0052
SECTION
SUB-SECTION
SUBJECT

SHE Management
Incident Investigations
SHE Incident Alerts

Doc. No.
Revision
Effective Date

Page No.

3800/FOR/0052 01 11.12.2019

1 of 1

SHE ALERT

Incident Description

While the Forklift Operator was trying to stack a three-way globe valve into a rack, it slid, fell, and broke the body York of the actuator, and bent the valve plug.

Body part / Nature of Damage

Broken three-way globe valve and bent valve plug

Preventative & Corrective Measures

- Work was stopped immediately.
- Where possible heavy materials should be stacked on lower racks.
- Secure loose items to the pallet before loading to avoid slips and falls.
- Employees must always adhere to safe work practices and supervisors must ensure that their teams adequately mitigate risks identified.

Safety Communication

Preliminary Findings?

- The three-way valve was not secured to the pallet hence it slid and fell as it was lifted to a height of more than 2.3 meters above ground.
- The Risk Assessment was done, and the hazard was also identified and mitigated by availing a spotter.
- The alco test was done, and the results were negative.
- The Operators authorization was valid

Broken Threeway Valve

Pictures

