



SHE Alert

SECTION

SUB-SECTION

SUBJECT

SHE Management

Incident Investigations

SHE Incident Alerts

Doc. No.

Revision

Effective Date

Page No.

3800/FOR/0052

01

11.12.2019

1 of 1

Safety First !

Classification

Property Damage

Where?

Section:

Culvert next to Salt Plant Workshop.

When?

Date: 08/01/2021

Time: 1420hrs

SHE Alert

Incident Description

EL&L truck registered B876 BBO slipped and drove into the culvert opposite the Salt Plant Workshop while on its way to offload coal.

Body part / Nature of Damage

Culvert broke off

Safety Communication

Preliminary Findings?

- The road condition was wet and slippery due to the recent rains, thus causing the trucks right front wheel to slide into the culvert.
- The intersection is narrow making it difficult for trucks with trailers to turn.
- The truck driver was also tested and results were negative.
- There is no chevron at the intersection.

Pictures



Preventative& Corrective Measures

- The incident was reported to relevant authorities.
- Other road users were notified to use alternative routes.
- The truck was removed from the incident scene.
- Chevrons signage was installed at the intersection.
- Drivers urged to exercise extra caution when driving in muddy conditions.
- The intersection joining Salt Plant, Stewart Motors and Utilities needs to be increased.