



SECTION
SUB-SECTION
SUBJECT

SHE Management
Incident Investigations
SHE Incident Alerts

Doc. No.

Revision

Effective Date

Page No.

3800/FOR/0051

01

16.09.2019

1 of 1

SAFETY FIRST !

SHE ALERT

Classification

Medical Treatment Injury

Where?

Section:
Rigging

Equipment:
Eyebolt on a motor

Incident Description

Whilst trying to unfasten an eyebolt from a motor using a spanner the injured's left palm got trapped between the eyebolt and the wrench resulting in a cut.

When?

Date: 27/08/2021
Time: 08:00 hrs.

Body part / Nature of Damage


- Left palm

SAFETY COMMUNICATION

Preliminary Findings?

- The injured used the wrong tool to unfasten the eye bolt.
- The injured should have used a longer tool to unfasten the stuck eye bolt for leverage and safety.
- The eyebolt was stuck in the threads and broke as result of the pressure exerted on it

PICTURES



Corrective/Preventive Action

- The activity was immediately stopped.
- The incident was reported to relevant authorities.
- The injured was taken to the mine clinic for further assistance.
- The incident was briefed to all employees in the section.
- People must always use the right tools when performing a task.