

SECTION SUB-SECTION SUBJECT SHE Management Incident Investigations SHE Incident Alerts Doc. No.
Revision
Effective Date
Page No.

3800/FOR/0051 01 16.09.2019 1 of 1

SAFETY FIRST!

Classification

First Aid Injury

SHE ALERT

Incident Description

Whilst loading a flatbed, a temporary

Where?

Packaging Attendant sustained a right

shoulder sprain after stepping on an unsecured

hatch/trapdoor.

Soda Ash Bagging

Section:

Equipment: N/A

When?

Date: 13/04/2021 **Time:** 09:45 hrs.

Body part / Nature of Damage

Sprain on right shoulder

Corrective/Preventive Action

- The activity was immediately stopped.
- The incident was reported to the relevant authorities.
- The injured was taken to the mine clinic for further assistance.
- Re-brief all crews on Loading Procedure.
- Enforce inspection of flatbeds by Packaging Attendants before application of dunnage.
- Supervisors to enforce the application of dunnage plastic by Packaging Attendants.
- Engagement with customers to ensure their trucks and flatbeds are in good condition.

SAFETY COMMUNICATION

Preliminary Findings?

- The injured had not undergone job specific induction.
- The truck was not inspected before application of dunnage plastic.
- Dunnage plastic was applied by the truck driver which is a breach of company procedure.

PICTURES



