16.09.2019 1 of 1

SAFETY FIRST!

Property Damage

Soda Ash Bagging

Customer Truck Tyre and

Equipment:

Soda Ash handrail

SHE ALERT

Classification **Incident Description**

Whilst positioning his truck to load, a Smartways truck driver hit the Soda Ash handrail and punctured the front left tyre of his truck.

When?

Where?

Section:

Date: 7/07/2021 **Time:** 22:00 hrs.

Body part / Nature of Damage

N/A

Corrective/Preventive Action

- The activity was immediately stopped.
- The incident was reported to the relevant authorities.
- The tyre was replaced, and the truck was checked for defects before being allowed to load.

SAFETY COMMUNICATION

Preliminary Findings?

- The driver was Alco tested and the results were negative.
- The driver was in possession of a valid driver's license.
- The truck driver made a misjudgement whilst trying to position the truck and drove over the handrail.

PICTURES



