

SHE Alert SECTION SUB-SECTION **SUBJECT**

SHE Management Incident Investigations SHE Incident Alerts

Doc. No. Revision **Effective Date** Page No.

3800/FOR/0052 11.12.2019

1 of 1

Safety First!

Incident Description

SHE Alert

Preliminary Findings?

Safety Communication

Pictures

Ground Pollution

Classification

Where? Sewage Treatment Plant

Section: SHE

When?

Date: 08/0/2021 Time: 0735hrs

Sewage effluent overflowed from septic tanks resulting in pollution of surrounding environment.

Ground pollution

Body part / Nature of Damage

Preventative & Corrective Measures

- The incident was reported to the Supervisor and maintenance teams.
- The plant was by-passed to the maturation ponds to prevent further pollution of the environment.
- Troubleshooting commenced to identify and rectify the cause of the fault

Recycle sump found on high-high mode indicating high levels of water in the sump.

- Water level in all the septic tanks was high.
- The plant was running with trickling filter feed pump (PC 1001) and Clarifier feed pump (PC 1003) at the time of the spill.

