



SHE Alerts 0052

SECTION

SUB-SECTION

SUBJECT

SHE Management

Incident Investigations

SHE Incident Alerts

Doc. No.

Revision

Effective Date

Page No.

3800/FOR/0052

01

11.12.2019

1 of 1

Safety First !

SHE Alert

Safety Communication

Pictures

Classification

Property Damage

Where?

Section:

Wellfield

Equipment:

LDV-Reg B192 BCN

When?

Date: 24/03/2022

Time: 1130hrs

Incident Description

Whilst driving on a gravel road along the potable/brackish water pipeline a wellfield operator lost control of his vehicle and crashed into the nearby trees.

Nature of Damage

Dents on the right side bodywork, and a right mirror broken.

Preliminary Findings?

- The operator was in possession of valid authorization.
- Pre-start checklist was conducted and there were no defects on the vehicle.
- The driver was Alco Tested and results were negative.
- Overspeeding - Vehicle control system indicated (Telematics) indicated that at the time of the incident the vehicle was travelling at 105km/h.

Corrective and Preventative Actions

- Relevant authorities were notified of the incident.
- The operator was taken to the mine clinic for further medical assessment and released back to work.
- Employees of the Section were briefed on the incident and sectional Baseline Risk Assessment (BRA).
- Operators of vehicles encouraged to adhere with stipulated road traffic speed limits.

