



SAFETY TOPIC - MARCH 2023

**ADHERE TO PERSONAL PROTECTIVE EQUIPMENT (PPE) REQUIREMENTS IN THE
WORKPLACE**



The following PPE must be worn when entering:

Plant Area

- ✓ Hard hat
- ✓ Reflective vest, coat, T-shirt, or shirt
- ✓ Overall or long trouser
- ✓ Ear plugs
- ✓ Safety glasses
- ✓ Steel toe boots covering the ankle
- ✓ Dust masks where necessary

Workshops & Materials Section

- ✓ Steel toe boots covering the ankle
- ✓ Goggles and ear plugs where necessary
- ✓ Hard hat when entering the warehouse and/or when stacking items at height.

MQWM Act reg 30(d): Every person at or in a mine, quarry or works shall, at all times when the nature of their work requires use of all devices and wear all articles of clothing designated for his protection or required to be used and worn by him under these Regulations.

Marang W. Molatlhegi


SHE Manager

Date: 28/2/23