



Rev 03  
Drafted by: Botash Maint Planner



Botswana Ash (Pty) Ltd

**Drafted by: Slingshot Consultancy**  
**STATUS DATE: 6-May-23**



### TOP 5 RISKS

- 1) Late material deliveries
- 2) SA Works - Turnaround
- 3) Equipment availability
- 4) Quality
- 5) Works execution risks

Based on spares available

LOOK AHEAD SCOPE OF WORKS	POSSIBLE RISKS	MITIGATIONS ON RISKS
Solar Ponds cleaning		
PS7, ST1 & 2 Insp flush line		
T-Brine Line Valves		
ST1 & 2(N&S) Remove & Overhaul pumps		
Salt Washing cleaning		
Road hopper pump & Pipes lines		
Discharge belt & Yard feed conveyors		
Single Boom stackers		
Side Arm reclaimer		
Wash Feed conveyor		
T-Brine heat exchanger pipes		
Bucket elevator		
#1, 2 & 3 Wash Tanks - Rubber linings		
Electrical maint - Cyclone Pumps		
Coal handling conveyors structures		
Salt & Drying - cleaning silos 1, 2, 3		
Salt screens		
Feed conveyors		
Vibrator Distributors		
Coarse & Milles Salt Plant cleaning		