



## SHE Alerts 0052

SECTION

SHE Management

Doc. No.

3800/FOR/0052

SUB-SECTION

Incident Investigations

Revision

01

SUBJECT

SHE Incident Alerts

Effective Date

11.12.2019

Page No.

1 of 1

## Safety First !

## SHE ALERT

## Safety Communication

## Pictures

### Classification

First Aid injury

### Where?

**Location:** Sie yuan Electric Site

**Section:** Projects

### When?

**Date:** 22/03/2024

**Time:** 08:00hrs

### Incident Description

An employee sustained an abrasion on his right eye socket after being hit by a gum pole whilst loading the poles from a Light Duty Vehicle into truck.

### Body part / Nature of Damage

Abrasion on the right side of the eye socket

### Preliminary Findings?

- Risk assessment was inadequate as loading activity and its risks were not identified.
- Lack of clear instructions by both site supervisor and his foreman about tasks assigned to their employees.
- Alco-testing was conducted to the crew and results were negative.

## Preventative& Corrective Measures

- The activity was stopped, and all employees were briefed about the incident.
- First aid was administered on site.
- The incident was reported to relevant authorities and the injured was taken to the mine clinic for further medical assessment.
- Supervisors must raise awareness on risk management.
- Employees to be re-briefed on manual Loading and Offloading procedure.
- Supervisors to improve supervision.



Abrasion on right side of eye socket