SHE Alerts 0052 **SECTION** SUB-SECTION **SUBJECT**

SHE Management Incident Investigations **SHE Incident Alerts**

Doc. No. Revision **Effective Date** Page No.

3800/FOR/0052

01 11.12.2019 1 of 1

Safety First!

SHE ALERT

Safety Communication

Preliminary Findings?

Pictures

Classification

High Potential Incident

Where?

Section:

Salt Plant and Garage

Area:

When?

Road infront of LBB yard

Date: 29/11/2021

Time: 1300hrs

Incident Description

Whilst carrying new empty bags from Procurement a Front-End Loader (FEL) hit an LDV on the road infront of the LBB yard.

Body part / Nature of Damage

Nudge bar and bonnet cover of LDV

Preventative& Corrective Measures

- The incident was reported to the relevant personnel.
- Salt Plant and Garage employees were briefed on the incident.
- Re Brief employees Salt Plant and Garage employees on MQWM Act Reg 26.29 & 30
- Operators of mobile equipment must always park them in a safe area.
- All loads must be secured when being transported.
- People must always use the right equipment when performing their tasks
- Employees must take responsibility for their own safety and that of others at all times

- Prestart checklists for both machines had been done, and the machines were safe for use.
- Both operators of the machinery have valid authorizations.
- Use of wrong equipment- the FEL was used to carry stacks of empty bags which forced the operator to lift the bucket higher obstructing his view.
- Unsafe Act the FEL operator continued with the task despite the bags obstructing his view.
- The LDV was carrying unsecured loads (Oil Drums) which fell on the side prompting the driver to stop.
- Negligence the LDV driver parked his vehicle in the middle of LBB road to fix the drums which had fallen off taking the without necessary precautions.
- The driver of the LDV and FEL were alco tested and the results were negative.



