



SECTION  
SUB-SECTION  
SUBJECT

SHE Management  
Incident Investigations  
SHE Incident Alerts

Doc. No.

Revision

Effective Date

Page No.

3800/FOR/0051

01

16.09.2019

1 of 1

## SAFETY FIRST !

## SHE ALERT

## SAFETY COMMUNICATION

## PICTURES

### Classification

Environment Incident

### Where?

#### Section:

Electrical – LBB yard

#### Equipment:

N/A

### When?

**Date:** 14/04/2021

**Time:** 10:00 hrs.

### Incident Description

Whilst trying to move a 210litre drum of transformer oil, the bottom cover broke and spilled the oil on to the ground.

### Body part / Nature of Damage

200L of transformer oil spill

### Corrective/Preventive Action

- The activity was immediately stopped.
- Incident was reported to the relevant authorities.
- Contaminated ground was excavated.
- Employees of the section were briefed on the incident.
- Supervisors to enforce the storage of chemicals in bunded areas.

### Preliminary Findings?

- The bottom cover of the drum was corroded as a result of being stored on the ground for an extended period.
- Poor housekeeping the drum was stored directly on the ground instead of bunded area.
- Violation of procedure, the transformer oil was stored on the ground instead of a bunded area.