

**SHE Alerts 0052**

SECTION

SHE Management

Doc. No.

3800/FOR/0052

SUB-SECTION

Incident Investigations

Revision

01

SUBJECT

SHE Incident Alerts

Effective Date

11.12.2019

Page No.

1 of 1

Safety First !**SHE ALERT****Safety Communication****Pictures****Classification****Incident Description****Preliminary Findings?**

Property Damage

Whilst offloading coal ,the rear bucket of the truck tilted into the coal stockpile and fell on its side.

- Hydraulic hose on the boom failed.
- The operator was in possession of a valid driver's license .
- The operator was also tested and results were negative.
- Pre-start checklist was not conducted on the truck.

Where?

Location : Coal stockpile
Section: Marketing-Enisiana Simba

When?**Nature of Damage**

Date: 25/10/2022
Time: 09:30hrs

- Hydraulic hose

Corrective Measure

- Supplier hosts to inspect all contracted trucks to ensure they are fit for use.



bucket of trailer