



SHE Alert

SECTION

SUB-SECTION

SUBJECT

SHE Management

Incident Investigations

SHE Incident Alerts

Doc. No.

Revision

Effective Date

Page No.

3800/FOR/0052

01

11.12.2019

1 of 1

Safety First !

Classification

Property Damage

Where?

Section: Light Vehicle Workshop

When?

Date: 17/01/2021

Time: 1015hrs

SHE Alert

Incident Description

Whilst trying to park the bus for washing at the light vehicle workshop, the right front tyre of the bus drove off the pavement and hit morooka with its right mirror.

Body part / Nature of Damage

Right mirror of bus and left door window of the Morooka

Preventative& Corrective Measures

- The incident was reported to relevant authorities.
- The bus was removed from the incident scene.
- Drivers urged to drive on designated roads.

Safety Communication

Preliminary Findings?

- Driver was also tested and the results were negative.
- Driver has a valid authorization.
- The area where the driver was parking the bus was narrow.
- The driver misjudged the area of the pavement and drove the front wheel of the bus off the pavement, hitting the Morooka with its right mirror.

Pictures

