



## SHE Alerts 0052

SECTION

SHE Management

Doc. No.

3800/FOR/0052

SUB-SECTION

Incident Investigations

Revision

01

SUBJECT

SHE Incident Alerts

Effective Date

11.12.2019

Page No.

1 of 1

## Safety First !

## SHE ALERT

## Safety Communication

## Pictures

### Classification

Environmental Incident

### Where?

Location : PS2

Section: Solar Ponds-  
Edgeworks Inc

### When?

Date: 06/11/2022

Time: 15:52hrs

### Incident Description

Whilst offloading salt with a tipper truck, the seal of tipping cylinder broke and splashed approximately 20 litters of hydraulic oil on to the ground.

### Body part / Nature of Damage

- Ground contamination

### Preliminary Findings?

- The Operator was in possession of a valid authorization.
- The Operator was also tested and the results were negative.
- The Operator used the wrong checklist to check the machine.
- Approximately 20L of hydraulic oil was spilt on the ground.
- The Compensator valve failed resulting in the Tipping cylinder breaking.

## Preventative & Corrective Measures

- The task was stopped, and incident reported to all relevant authorities.
- The incident was briefed to employees of the section.
- Contaminated ground was removed and disposed at the Salvage Yard.
- Edgeworks to develop and ensure adherence to a planned maintenance schedule for all their trucks.



Broken Tipping cylinder through  
truck bucket