



SECTION
SUB-SECTION
SUBJECT

SHE Management
Incident Investigations
SHE Incident Alerts

Doc. No.

Revision

Effective Date

Page No.

3800/FOR/0051

01

16.09.2019

1 of 1

SAFETY FIRST !

SHE ALERT

SAFETY COMMUNICATION

PICTURES

Classification

First Aid Injury

Incident Description

Whilst clearing a workbench, channel iron slipped from the Artisan Boilermaker's left hand and struck him on his left knee.

Where?

Section:

Fabrication

Equipment:

N/A

When?

Date: 07/07/2021

Time: 19:40 hrs.

Body part / Nature of Damage

- Left Knee

Preliminary Findings?

- Inadequate Pre- Task Risk Assessment
–Failure to identify and mitigate against the risk of manual handling in the risk assessment.
- The injured was using the incorrect type of gloves (welding gloves) for manual lifting which do not have sufficient grip.
- The injured lifted the load using the wrong position, hence when the load slipped it struck him on the knee.

Corrective/Preventive Action

- The activity was immediately stopped.
- The incident was reported to relevant authorities.
- The injured was taken to the mine clinic for further assistance.
- The incident was briefed to all employees in the section.