



SHE Alerts 0052

SECTION

SHE Management

Doc. No.

3800/FOR/0052

SUB-SECTION

Incident Investigations

Revision

01

SUBJECT

SHE Incident Alerts

Effective Date

11.12.2019

Page No.

1 of 1

Safety First !

SHE ALERT

Safety Communication

Pictures

Classification

Incident Description

Preliminary Findings?

First Aid Injury

Whilst crossing the trench by Crystallization tank, a Botswana Railways employee slipped and fell sustaining a sprain on her right wrist.

- **Unsafe condition** – there is a leak on the Bitterns line.
- The injured was wearing worn-out boots despite being issued new ones.

Where?

Location: Soda Ash
Section: Marketing

When?

Body Part/Nature of Damage

Date: 07/11/2022
Time: 0800hrs

Right wrist

Preventative & Corrective Measures

- The incident was reported to the responsible personnel.
- The injured was taken to the clinic for medical assistance and later referred to Francistown for assessment.
- All unsafe conditions to be isolated and attended to at the soonest time.
- Employees to assess the area before accessing them.



Wet paved surface