



## SHE Alerts 0052

SECTION

SHE Management

Doc. No.

3800/FOR/0052

SUB-SECTION

Incident Investigations

Revision

01

SUBJECT

SHE Incident Alerts

Effective Date

11.12.2019

Page No.

1 of 1

## Safety First !

## SHE ALERT

## Safety Communication

## Pictures

### Classification

LTI

### Where?

**Location:** Eastern Stacker

**Section:** Salt Plant

### When?

**Date:** 25/04/2024

**Time:** 19:40hrs

### Incident Description

A temporary employee's right hand got trapped between the stacker discharge conveyor pulley and the discharge plate, resulting in an injury.

### Nature of Injury

Crush injury on right hand

### Preliminary Findings?

- The injured right-hand fingers went through the gap between the conveyor pulley and the discharge plate while trying to collect a fine salt 50kg bag from the discharge plate.
- The conveyor was stopped using the emergency stop button to free the injured's hand.
- The injured was putting on safety gloves.

## Corrective/Preventative Measures

- The task was stopped, and the bagging crew was briefed.
- Increase the gap between the discharge plate and the conveyor
- The injured person was taken to Francistown Academic Hospital for further assessment and treatment.



The gap between the conveyor pulley and the discharge plate.