



SHE Alerts 0052

SECTION

SHE Management

Doc. No.

3800/FOR/0052

SUB-SECTION

Incident Investigations

Revision

01

SUBJECT

SHE Incident Alerts

Effective Date

11.12.2019

Page No.

1 of 1

Safety First !

SHE ALERT

Safety Communication

Pictures

Classification

First Aid Injury

Where?

Location : Fabrication Workshop

Section: Fabrication

When?

Date: 17/05/2023

Time: 11:30hrs

Incident Description

A welder sustained an injury after a slag particle got into his right eye whilst chipping on a stainless steel GN01 drop chute.

Body part / Nature of Damage

- Slag particle in his right eye

Preliminary Findings?

- **Incorrect use of PPE** – The welder did not use the filter lens of the helmet but instead he raised the entire helmet from his face exposing his eye to falling particles of slag.

Chipping with the filter lens raised and clear lens covering the eyes

Chipping with the helmet removed from the face exposing eyes to injury

Preventative & Corrective Measures

- The incident was reported and the injured was taken to the mine clinic for medical assistance
- The incident was briefed to all employees of the section.
- Employees must always ensure the proper use of the required PPE when performing their tasks.

