



SHE Alerts 0052

SECTION

SUB-SECTION

SUBJECT

SHE Management

Incident Investigations

SHE Incident Alerts

Doc. No.

Revision

Effective Date

Page No.

3800/FOR/0052

01

11.12.2019

1 of 1

Safety First !

SHE ALERT

SAFETY Communication

Pictures

Classification

First Aid Injury

Where?

Section:

Security Section

Equipment:

Cadac cylinder

Incident Description

A Security Officer got her left little finger trapped between a 9 kg LPG cylinder and truck stairs whilst conducting an inspection on a customer's truck.

Preliminary Findings?

- The Security Officer was alco-tested and results were negative.
- There was poor housekeeping in the truck cabin which resulted in a cylinder that was placed against the passenger door to fall onto the security officers finger when she was trying to gain access in to the cabin



When?

Date: 10/12/2023

Time: 0850 hrs.

Body part / Nature of Damage

Left Little Finger

Corrective & Preventative Measures

1. Activity was stopped immediately and first aid was administered to the Security Officer.
2. The injured was taken to the mine Clinic for further assistance.
3. Employees were briefed on the incident and rebriefed on the Baseline Risk Assessment.
4. Truck drivers to ensure that items in their cabins are properly stored and not placed against the cabin door.
5. The truck drivers must open doors for security officers to conduct inspections.

Injured finger

