



SHE Alerts 0052

SECTION

SHE Management

Doc. No.

3800/FOR/0052

SUB-SECTION

Incident Investigations

Revision

01

SUBJECT

SHE Incident Alerts

Effective Date

11.12.2019

Page No.

1 of 1

Safety First !

SHE ALERT

Safety Communication

Pictures

Classification

HP- Near Miss

Where?

Location: Washed Salt Stockpile

Section: Salt Plant

When?

Date: 18/04/2024

Time: 03:55hrs

Incident Description

The Botash dump truck almost fell off the salt piles when the truck reversed over the berm.

Nature of Damage

No damages

Preliminary Findings?

- The operator was getting ready to offload the first load at the washed salt stockpile.
- The operator reversed beyond the offloading point.
- There were no injuries sustained.
- The operator had valid authorization to conduct the operation.

Corrective Measures

- Employees must ensure good communication during task execution.
- Employees must ensure that all the risks identified during work are mitigated adequately.
- A recovery team was established to ensure safe retrieval of the machine.

