



SHE Alerts 0052

SECTION

SHE Management

Doc. No.

3800/FOR/0052

SUB-SECTION

Incident Investigations

Revision

01

SUBJECT

SHE Incident Alerts

Effective Date

11.12.2019

Page No.

1 of 1

Safety First !

SHE ALERT

Safety Communication

Pictures

Classification

First Aid Injury

Where?

Location : Stores yard

Section: Fabrication

Incident Description

Whilst trying to place a 3mm stainless steel sheet in position, a Boilermaker sustained a contusion and laceration on his left index finger after it was trapped between sheet and compactor roller.

When?

Date: 28/04/2023

Time: 13:40hrs

Body part / Nature of Damage

- Cut on the left index finger

Preliminary Findings?

- **Improper handling technique-**
The boilermaker instead of holding the metal sheet on top, he held it on the side which led to his hand being trapped at a nip point formed with the roller.
- **Inadequate risk Assessment** –
The risk of sustaining cuts during the task was identified how ever adequate controls were not implemented.

Nip point between metal sheet and roller where the fingers were trapped

Preventative & Corrective Measures

- The incident was reported to responsible personnel
- The incident was briefed to employees of the section.
- Employees must ensure proper handling techniques during work
- Employees must ensure all the hazards associated with their tasks are adequately controlled.

