



SHE Alerts 0052

SECTION

SHE Management

Doc. No.

3800/FOR/0052

SUB-SECTION

Incident Investigations

Revision

01

SUBJECT

SHE Incident Alerts

Effective Date

11.12.2019

Page No.

1 of 1

Safety First !

SHE ALERT

Safety Communication

Pictures

Classification

First aid injury

Where?

Location : Bagging

Section: Salt Plant

When?

Date: 25/08/23

Time: 1930 hrs.

Incident Description

Whilst loading 50kg bags of course salt a Bag Stacker stepped into a hole on the trailer of a truck.

Nature of Injury/ Nature Of Damage

Superficial abrasion and a sprain on the left ankle.

Preliminary Findings?

- Truck was inspected and declared fit to load by security.
- The truck trailer was defective, had a hole.
- The driver had a valid license.
- Driver was also tested and results were negative.

Preventative & Corrective Measures

1. Activity was stopped immediately
2. Incident was reported to relevant authorities
3. The injured was taken to the mine clinic for further assistance.
4. Customers must ensure that their trucks are fit for purpose.
5. Security and respective sections to thoroughly check trucks before loading and non compliant trucks denied access.

A hole on the truck base

