Classification

Where?

Property Damage

Location: Stores

Section: Garage

Date: 22/07/2022

Time: 15:30hrs

Workshop

When?

SHE Alerts 0052 **SECTION** SUB-SECTION **SUBJECT**

SHE Management Incident Investigations SHE Incident Alerts

Doc. No. Revision **Effective Date** Page No.

3800/FOR/0052

11.12.2019 1 of 1

Safety First! SHE ALERT

Incident Description

Whilst being towed from the Garage Workshop, a diesel bowser trailer decoupled from an light duty vehicle (LDV) and crashed into the Stores fence.

Body part / Nature of Damage

Stores fence

Preventative& Corrective Measures

- The incident was reported to the relevant personnel.
- The diesel bowser trailer was put out of use until all defects identified are fixed
- The section was briefed on the incident.
- Employees must not use defective equipment.
- Employees must be fully engaged when performing their tasks.
- Conduct a minewide inspection of all bowsers to ensure they comply.

Safety Communication

Preliminary Findings?

- of attention The Lack operator did not ensure that the trailer latch was fully secured on the LDV.
- Use of defective equipment The safety chain of the trailer was broken.
- The was no fire extinguisher on the diesel bower.
- The driver was in possession of a valid driver's authorization.
- The driver was alco tested and results were negative.

Pictures



Damaged stores fence