



SHE Alerts 0052

SECTION

SUB-SECTION

SUBJECT

SHE Management

Incident Investigations

SHE Incident Alerts

Doc. No.

Revision

Effective Date

Page No.

3800/FOR/0052

01

11.12.2019

1 of 1

Safety First !

SHE ALERT

Safety Communication

Pictures

Classification

First Aid Injury

Where?

Section: Utilities Plant

Location: Boiler 1

Incident Description

A temporary employee sustained an abrasion on his right shin after his leg went between the boiler tubes when he stepped on the edge of a shutter board that was used as walking platform in boiler 1.

When?

Date: 13/04/2022

Time: 0945hrs

Body Part/Nature of Damage

Abrasion on right shin

Preliminary Findings?

- **Inattentiveness** - The injured was not paying attention whilst walking, he stepped on the edge of the shutter board and his leg went through the boiler tubes.
- The shutter board was not covering the whole walking platform.

Preventative& Corrective Measures

- Work was stopped immediately
- The incident was reported to the responsible personnel.
- The injured was taken went to the clinic for further medical assistance
- Employees must always remain alert when working.
- The incident was briefed to section employees.



Shutter board used for providing walking platform on the boiler tubes