



SHE Alerts 0052

SECTION

SUB-SECTION

SUBJECT

SHE Management

Incident Investigations

SHE Incident Alerts

Doc. No.

Revision

Effective Date

Page No.

3800/FOR/0052

01

11.12.2019

1 of 1

Safety First !

SHE ALERT

Safety Communication

Pictures

Classification

First Aid Injury

Where?

Section: Utilities Plant

Location: Boiler 1

When?

Date: 13/04/2022

Time: 1100hrs

Incident Description

Whilst facing upward assisting with installation of metal sheets at boiler 1,a temporary employee sustained an eye injury on the right after foreign particles fell from an overhead beam and got into his eye.

Body Part/Nature of Damage

Foreign particle in right eye

Preliminary Findings?

- Despite wearing safety goggles, the foreign object managed to find its way into the injured eye.

Preventative& Corrective Measures

- Work was stopped immediately
- The incident was reported to the responsible personnel.
- The injured washed his eye at the emergency eye washer station.
- The injured was taken to the clinic for further medical assessment.
- Employees must wear correct PPE all time.

