



## SHE Alerts 0052

SECTION

SUB-SECTION

SUBJECT

SHE Management

Incident Investigations

SHE Incident Alerts

Doc. No.

Revision

Effective Date

Page No.

3800/FOR/0052

01

11.12.2019

1 of 1

## Safety First !

## SHE ALERT

## Safety Communication

## Pictures

### Classification

Property Damage

### Where?

Section: Store

Location: Stores Yard

### When?

Date: 22/09/2022

Time: 1640hrs

### Incident Description

Whilst trying to lift a cable drum it rolled from the forklift and damaged the Stores backyard parameter wall.

### Damage

- Dura wall

### Preliminary Findings

- Prior to the incident the team had unreeled 30m out of 110m of PILC electrical cable (95mm x 3).
- To prevent the cable from kinking, the team lifted the cable drum using a forklift and it rolled and hit the dura wall.
- Use of wrong equipment- a forklift instead of crane was used to lift cable the drum.
- The operator was also tested and the results were negative.
- The operator has valid authorization.



Damaged Area

## Actions Taken Following The Incident

- Work was stopped and riggers were engaged to reposition and place the cable drum on the stand.
- Civils crew was dispatched to restore the damaged wall.