

SHE Alerts 0052

SECTION SHE Management

SUB-SECTION Incident Investigations

SUBJECT SHE Incident Alerts

Doc. No.Revision
Effective Date

Page No.

3800/FOR/0052 01 11.12.2019

1 of 1

Safety First!

SHE ALERT

Safety Communication

Picture

Classification

Property Damage

Where?

Location : Stores

Section: Materials

Management

Date: 24/09/2022

When?

Time: 1830

Incident Description

A kudu jumped onto the Stores vehicle B 353 BCH whilst being driven home from work.

Body part / Nature of Damage

Windshield and bonnet

Action Taken Following The Incident

- The incident was reported to all relevant authorities.
- The driver and passenger were taken to the clinic for medical assistance.
- Extra caution must be taken when driving at night.

Preliminary Findings?

- There were two occupants in the vehicle and no serious injuries were sustained.
- The fleet management system indicated that the vehicle was travelling at an average speed of 40km/h and a maximum speed of 72 km/h during the journey.
- Vehicle prestart checklist was done, and no defects were detected.
- The driver was in possession of a valid authorization.
- The driver was alco tested and the results were negative.

