



SHE Alerts 0052

SECTION

SHE Management

Doc. No.

3800/FOR/0052

SUB-SECTION

Incident Investigations

Revision

01

SUBJECT

SHE Incident Alerts

Effective Date

11.12.2019

Page No.

1 of 1

Safety First !

SHE ALERT

Safety Communication

Pictures

Classification

First Aid injury

Where?

Location : Firing floor(Boiler 1)
Section: Utilities Plant

When?

Date: 14/05/2023
Time: 11:00hrs

Incident Description

A semi-skilled fitter sustained a superficial burn on his neck after a metal dross fell on him from coal bunker fourth floor.

Body Part/Nature of Damage

- Neck

Preliminary Findings?

- There was no communication between workers at floor number four and floor number two.
- Upon arrival, the area was not fully barricaded and the injured managed to get access.
- Fire blankets were not covering steel boards.

Preventative& Corrective Measures

- The injured was taken to the mine clinic where he was treated and sent back to work.
- Employees should always communicate and fully barricade areas where they work.
- Employees must not remove any barricade unless instructed by supervisor to do so.

